



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JJN-614

### SECTION I : IDENTIFICATION

#### 1. Name

**Present** : Mansukh Rai Mor Haveli  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 75° 4' E

**LATITUDE** 28° 13' N

#### **Address**

Near-Podar Gate, Ward No.-28

: **Village (village code)**

**Post** : Nawalgarh

**District:** Jhunjhunu

**State** : Rajasthan

**PIN:** 333042

#### **Approach**

: The Haveli situated in Nawalgarh & well connected by train & bus services.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)  
**Haveli**

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is an old haveli embellished with an exuberance of Rajasthani fresco at the entrance. The raised platform on either side of the entrance has decorative paintings. There is an image of a diety on the Lalat-bimba. The volt of the cusped arch at the entrance is studded with profusion of Rajasthani fresco.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** :  
**Past** :

#### 5. Age (Source)

---

**PERIOD** :  
**YEARS** : 18<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :  
**Private** :  
**Any other (Please specify)** :  
**Name** : Mansukh Rai Mor  
**Address** : Near-Podar Gate, ward-28, P.O-Nawalgarh. Dist-Jhunjhunu  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** : Living used for Residential purpose
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |                     |
|-------------------------------------|---------------------|---------------------|
| <input checked="" type="checkbox"/> | Architectural       | Fresh dressed stone |
| <input type="checkbox"/>            | Archaeological      |                     |
| <input type="checkbox"/>            | Historical          |                     |
| <input type="checkbox"/>            | Religious           |                     |
| <input type="checkbox"/>            | Any other (specify) |                     |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context** : \* **Drawings** (Attach extra sheet if necessary)  
**Urban / Rural Setting** : Urban  
**Surroundings** : **Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 02  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The Haveli is oriented East-West and faces West  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : The entrance is adorned with cusped arch and Rajasthani frescos which are uniform in colour and composition.  
  
Interiors : There are alcoves and lime-plaster coating the interior.  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate
- Material of Construction** : Brick and stone

### 11. Condition Assessment

---

**In General** : **Good / Fair**  
Good

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

#### **In Brief (Attach extra sheet if necessary):**

Peeling of plaster and discolouration. Improper electric fittings.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**